

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

MICHAEL O. LEAVITT Governor

OLENE S. WALKER Lieutenant Governor

Representatives Present During the Inspection			
Company	Gary E. Gray Resident Agent		
OGM	Karl Houskeeper Reclamation Specialist III		

Inspection Report

Permit Number:	C0070041
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, October 08, 2003
Start Date/Time:	10/8/2003 9:00:00 AM
End Date/Time:	10/8/2003 11:00:00 AM
Last Inspection:	Thursday, September 18, 2003

Inspector: Karl Houskeeper, Reclamation Specialist III

Weather: Clear, ~Temp 65 Degrees F

Accepted by: pgrubaug 10/24/2003

Permitee:	WEST	RIDGE	RESOL	JRCES
Operator:	WEST	RIDGE	RESOL	JRCES

Site: WEST RIDGE MINE

Address: PO BOX 1077, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

4,307.63	Total Permitted	
29.06	Total Disturbed	
	Phase I	
	Phase II	
	Phase III	

Mineral Ownership	Types of Operations
-------------------	---------------------

moral o milotomp	. Jpcc c. opciano.
✓ Federal	Underground
✓ State	Surface
☐ County	Loadout
Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature:	Date	Wednesday, October 08, 2003
	24.0	

Karl Houskeeper, Reclamation Specialist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 08, 2003

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.1	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Date: Wednesday, October 08, 2003

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Division Order for Highwall Elimination at the West Ridge Mine has not been resolved. The operator is in the process of addressing additional items to satisfy the Division Order.

2. Signs and Markers

The Mine ID signs at the Pump House and at the Mine Site entrance are in place. The operator's phone number prefix has changed from 564 to 888. This change needs to be reflected on the ID signs. The other information on the ID signs is accurate. All other signs and markers observed during the inspection are in accordance with the approved MRP and the coal rules.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The MRP specifies that a catwalk be present in cell B of the sediment pond for monitoring purposes. This item was discussed during the partial inspection. A catwalk is being constructed by a steel fabricator and will be installed in cell B. The catwalk fabrication is almost completed, and the operator anticipates that the cat walk will be installed before the next inspection.

4.d Hydrologic Balance: Water Monitoring

The second quarter 2003 water quality information is in the EDI website and is uploaded. A review of the EDI website shows that there is third quarter 2003 information present, but it has not been uploaded. Water monitoring is current.